INDAVER

Ringaskiddy
Resource Recovery Centre

VOL 4

Environmental Impact Assessment Report | 2019
Appendices



Delivering Sustainable Waste Treatment Solutions For a Growing Population

ARUP

Preface

This Environmental Impact Assessment Report (EIAR) for the proposed Ringaskiddy Resource Recovery Centre consists of four volumes, of which this is the fourth:

Volume 1 Non-Technical Summary (NTS)

Volume 2 EIAR (Main Text)

Volume 3 Figures

Volume 4 Appendices

Volume 4 List of Appendices

1 Introduction
1.1 Letter from An Bord Pleanála, 23 December 2015
1.2 Consultation for Planning Application 2016
1.3 IE Licence Notice to Cork County Council
1.4 An Bord Pleanála Order (Planning Decision and Conditions) May 2018
1.5 EIA Legislation Compliance Matrix
1.6 EIAR Competent Experts
1.7 IE Licence Consultation Sample Letter
1.8 EIA Portal Confirmation Email

3 Alternatives
3.1 Planning Report, In Relation to Industrial Lands Within Metropolitan Cork
3.2 Fichtner Heat Network Report

4 Description of the Proposed Development
4.1 List of Waste (LoW) Codes of Waste Accepted by Indaver
4.2 Furnace Start Up and Shut Down Procedures
4.3 Interlock System
4.4 Compliance with Best Available Techniques (BAT)

5 Construction Activities
5.1 Construction Environmental Management Plan

6 Population and Human Health
6.1 Hazard Identification and Risk Assessment for Resource Recovery Centre, Ringaskiddy
6.2 Soil dioxin and dibenzofuran (PCDD/F) monitoring programme
6.3 Modelling of PCDD/F Intake for the proposed development

7 Roads and Traffic
7.1 Junction Analysis Results
7.2 Staff Mobility Management Plan (2015)
7.3 HGV Booking System Step-by-Step Process Flowchart

8 Air Quality

8.1 Air Quality Study by AWN

8.2 Description of AERMOD Model

8.3 Air Quality Impact from Traffic Sources

8.4 Cumulative Impact Assessment

8.5 Sensitivity Assessment of Modelling Input Parameters

8.6 Process Information

8.7 Detailed NO_x Process Calculations

8.8 Wind Turbine Interactions

8.9 Air Quality Response - Attachment 2 to Third Party Submissions Response Oct 2017

10 Noise and Vibration

10.1 Noise Monitoring Results

12 Biodiversity

12.1 Flora Survey - Species List

12.2 Winter and Breeding Bird Surveys

12.3 Mammal Surveys

12.4 Intertidal Survey

12.5 Site Synopsis for Natura 2000 Sites

12.6 Guidelines for Assessment of Ecological Impacts of National Road Schemes (National Roads Authority, 2009)

13 Soils, Geology, Hydrogeology, Hydrology and Coastal Recession

13.1 Soil and Hydrogeological Investigation by KT Cullen & Co Report (November 2000 and January 2001)

13.2 Hydrogeological Assessment for Hammond Lane Metal Company by O'Callaghan Moran & Associates (2011)

13.3 Coastal Erosion Study, Arup (2016)

13.4 Flood Risk Assessment by Arup (2019)

13.5 Coastal Erosion Report Addendum: Assessment of December 2015 Slope Instabilities, Arup (2016)

13.6 Coastal Expert Review of Arup Coastal Erosion Study (2016)

13.7 Witness Statement of Julie Ascoop, Maritime Engineer, Arup (2016)

13.8 Gobby Beach Site Visit Report, Arup (2018)

14 Archaeology Architecture & Cultural Heritage

14.1 Archaeology Architecture & Cultural Heritage - Correspondences

14.2 Archaeology Architecture & Cultural Heritage - Excavations

14.3 Archaeology Architecture & Cultural Heritage - Local Cultural Heritage of Study Area

14.4 Archaeology Architecture & Cultural Heritage - Descriptions of Archaeological Sites

15 Material Assets

15.1 RFI Response DBS Consulting Helicopter Navigation Report

15.2 RFI Response Aviation Safety Report

15.3 Department of Defence Letter to ABP July 2017